eGTouch 🙁		
Setting Tool Display Edge Misc	eGalaxTouch : USB C	ontroller
	Edge Compensation	h Hardware
nzation curve	General	Setting Tools
	Linearization Curve	
tion	A Pointe Calibration	Do 4 points alignment to match disp
ABts Cal Do 4 points alignment	4 Points Calibration	
to match display.	C	Clear linearization parameter and do
inearization Do 9 or 25 points linearization	Clear and Calibrate	alignment.
Clear linearization narameter		Do 9 points linearization for better to
and do 4 points alignment.	Linearization	linearity.
Draw Test Do draw test to verify		Do draw test to yet the touch acc
the touch accuracy	Draw Test	Do draw test to verify the tooch act
the touch accuracy.		
the touch accuracy.		

Ubuntu

Windows

The EGalaxTouch tool can be found at the following links:

Ubuntu: <u>https://www.eeti.com/drivers_Linux.html</u> Current Version: eGTouch_v2.5.13219.L-x

Windows: <u>https://www.eeti.com/drivers_Win.html</u> Current Version: 5.15.0.24308

- 1) Download and install the version that matches your Operating System.
 - Linux for all Linux/Ubuntu distributions.
 - Windows for all Windows Operating Systems (XP Windows 11)
- 2) Open the eGTouch/eGalaxTouch application and navigate to the **Tool(s)** tab.

- 3) Run the **Linearization** function.
 - The Linearization function will walk you through a 9-Point calibration.
 Please press and hold the Yellow Targets as they appear on the screen.
 - The test will complete after all 9 targets have been calibrated.
- 4) Check the calibration of the panel by using the **Draw** function under the **Tool(s)** tab.
- 5) Use the **Quit** button to exit the **Draw** function.
- 6) Uninstall the eGalaxTool Software from your system using **Windows Uninstaller** or **Ubuntu Package Manager**.

Windows Uninstaller:

- 1) Navigate to Control Panel > Programs > Uninstall a program
- 2) Select eGalaxTouch from the list of applications, and choose Uninstall
- 3) Confirm removing the selected application and all of its features.
- 4) A restart will be needed to finish the uninstall process.

Ubuntu Uninstaller:

- 1) Open Terminal
- 2) Type sudo apt-get remove eGTouchU and hit Enter
- 3) Confirm your password
- 4) A restart will be needed to finish the uninstall process.